## **Suzanne Steab - December 2009 Inspection Report**

From:

Karl Houskeeper

To:

mdavis@archcoal.com

Date:

1/4/2010 3:52 PM

Subject:

December 2009 Inspection Report

CC:

ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov

Attachments: SUFCO December 2009.pdf

Mike,

Attached is the December 2009 inspection report for the SUFCO Mine.

Thanks, Karl



#### State of Utah

#### Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

### Division of Oil, Gas & Mining

JOHN R. BAZA Division Director Representatives Present During the Inspection:

OGM Karl Houskeeper Environmental Scientist III

JON M. HUNTSMAN, JR. Governor GARY R. HERBERT Lieutenant Governor

# **Inspection Report**

Permit Number:	C0410002 PARTIAL		
Inspection Type:			
Inspection Date:	Tuesday, December 22, 2009		
Start Date/Time:	12/22/2009 7:30:00 AM		
End Date/Time:	12/22/2009 2:30:00 PM		
Last Inspection:	Tuesday, November 17, 2009		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Overcast/Snowing, Temp. 20 Deg. F.

InspectionID Report Number: 2232

Accepted by: jhelfric 12/28/2009

Permitee: CANYON FUEL COMPANY LLC Operator: CANYON FUEL COMPANY LLC

Site: SUFCO MINE

Address: 397 S 800 W, SALINA UT 84654

County: SEVIER

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

**Current Acreages** 

# Mineral Ownership **✓** Federal

#### **Types of Operations**

✓ Underground

☐ Surface

25,292.43	<b>Total Permitted</b>
48.43	<b>Total Disturbed</b>
	Phase I
	Phase II
	Phase III

✓ State ☐ County

☐ Loadout ☐ Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Leland Roberts SUFCO was in attendance during the Partial Inspection.

Area is snow covered.

Inspector's Signature:

Tuesday, December 22, 2009 Date

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0410002 Inspection Type: PARTIAL

Inspection Date: Tuesday, December 22, 2009

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	<b>V</b>		V	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	$\checkmark$		<b>✓</b>	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other	<b>7</b>	П	<b>V</b>	

**Inspection Continuation Sheet** 

Permit Number: C0410002 Inspection Type: PARTIAL

Inspection Date: Tuesday, December 22, 2009

Page 3 of 3

## 2. Signs and Markers

The ID signs located at the points of public access contained the necessary information.

# 4.b Hydrologic Balance: Sediment Ponds and Impoundments

Nelco Construction started initial work on the new sediment pond, but got wintered out.

#### 22. Other

Horizontal drilling amendment has been approved by the Division. Drilling is scheduled for the first part of January.